


|   |  |   |
|---|--|---|
|  <p>BioAssay Works<sup>®</sup><br/>www.bioassayworks.com</p> | <p><b>Material Safety Data Sheet</b></p> | <p>OPS-MSDS-KIM-LF-0001<br/>Date of Issue – August, 2010</p> <p>Page 1 of 1</p> |
|---|--|---|

1. The Sample Diluent Buffer of BioAssay Works' **Human KIM-1 and Rat Kim-1 Lateral Flow kits** contains 0.01 % ProClin 950.

Proclin is corrosive, causes eye damage and skin burns, can cause allergic skin reaction, may be harmful if inhaled, may be fatal if swallowed or absorbed through skin.

#### **4. FIRST AID MEASURES**

**Eyes:** Flush immediately with copious amounts of water for at least 15 minutes. Assure adequate flushing by separating eyelids with fingers. Get prompt medical attention but flush the eyes first.

**Skin:** Wash thoroughly with soap and water. Remove contaminated clothing and shoes.

**Ingestion:** Flush mouth if person is conscious. Call a physician. Never give anything by mouth to an unconscious person

**Inhalation:** Get fresh air immediately. If breathing becomes difficult, call a physician.

#### **ACCIDENTAL RELEASE MEASURES**

Absorb with absorbent paper. Clean spill area with soap and water and then disinfect. Dispose of materials according to local and national laws.

#### **HANDLING**

Handling: Do not eat, drink, smoke or apply cosmetics in laboratory areas. Do not mouth pipette reagents or samples by mouth. Avoid splashing and forming aerosols. Use reagents according to the product insert. Avoid extreme temperatures during transport.